December 19, 2013 130-2167

All Bid Holders of Record

RE: CITY OF EDINBURG
BID NUMBER 2014-40
CELL 5A CELL CONSTRUCTION, EDINBURG SANITARY LANDFILL
ADDENDUM NO. 2

Dear Recipient:

Golder Associates Inc (Golder), has prepared this Addendum No. 2 to the above-mentioned bid documents. This addendum forms a part of the bid documents and modifies the original "Invitation to Bid" dated December 2013.

Bidders must acknowledge receipt of this addendum in the space provided on the Bid Form, Item C on Page 00003-2 and 00003-7. Failure to do so may result in disqualification.

Addendum No. 2 consists of the clarification provided below.

1.0 CLARIFICATION

A question was asked regarding the bottom width of the site ditches that are shown on the plans as requiring cleaning. Below is a list of the ditched and the approximate width of each ditch:

- Unit 5, West Ditch: This is a wide flat cross section ditch with a bottom width of approximately 30 feet. Assume 1.5 feet of silt is to be removed from this ditch.
- Unit 5, North Ditch: This is a 3 foot deep ditch with a 4 foot bottom width and 3h:1v side slopes. Assume 1.5 feet of silt is to be removed from this ditch.
- Unit 6, North Ditch: This is a 5 foot deep ditch with a 2 foot bottom width and varying (steep) side slopes. Assume 1.5 feet of silt is to be removed from this ditch.
- Unit 6, West Ditch: This is a wide flat cross section ditch with a bottom width of approximately 35 feet. Assume 1.5 feet of silt is to be removed from this ditch.
- Unit 6, South Ditch: This is a 2 foot deep "v" ditch with a top width of 12 feet. Assume 2 feet of cut is needed on most of this ditch.

Sincerely,

GOLDER ASSOCIATES INC.

STATE OF TEXAS
12-19-13
W. E. GORDON
78933
REGISTERED PROFESSIONAL ENGINEER

Mark E. Roth
Associate

William E. Gordon, P.E.
Senior Engineer

cc: Ramiro L. Gomez, Jr., City of Edinburg

MER/WEG/weg

Golder Associates Inc.
F-2578

c:\users\kruthstrom\appdata\local\microsoft\windows\temporary internet files\content.outlook\u2r0q69w\addendum no 2 cell 5a (2).docx

Golder Associates Inc.
500 Century Plaza Drive, Suite 190
Houston, TX 77073 USA
Tel: (281) 821-6868 Fax: (281) 821-6870 www.golder.com

Golder Associates: Operations in Africa, Asia, Australasia, Europe, North America and South America